

SSO Notification List

January 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	1/2/2018	136 S Loudon Ave	21229	Rags, Roots	Dry		0	Heavy gray water and debris observed around the cleanout at the rear of the property.	6	Relieved 6" house connection choke with 15 ft of electric cable.	Performed house lateral CCTV inspection.	505343
2	1/2/2018	2300 James St	21230	Structural	Dry		1,598	Heavy gray water escaping broken pipe next to CSX tracks.	3,196	Repaired damage to pipe.	Performed CCTV inspection.	505407
3	1/5/2018	4016 Pinkney Rd	21215	Rags, Roots, Trash	Dry		183	Heavy gray water.	366	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	507325
4	1/6/2018	1700 Brentwood Ave	21202	Rags, Roots, Grease, Trash	Dry		176	Heavy gray water escaping manhole.	880	Relieved 8" mainline choke with 260 ft of pressure hose.	Performed mainline CCTV inspection.	507592
5	1/9/2018	3250 E Fayette St	21224	Rags, Grease, Trash	Dry		280	Heavy gray water flowing from manhole.	1,400	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed CCTV inspection.	509405
6	1/9/2018	1405 McCulloh St	21217	Rags, Grease, Trash	Dry		0	Gray water observed around the cleanout and alley at the rear of the property.	7	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	509492
7	1/10/2018	1619 Gwynns Falls Pkwy	21217	Rags, Roots	Dry		0	Heavy gray water observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 30 ft of electric cable.	Confirmed mainline and lateral are clear.	509781
8	1/11/2018	429 E 29th St	21218	Rags, Roots, Grease, Trash	Dry		0	Water observed around the cleanout.	7	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	510188
9	1/13/2018	2801 Kinsey Ave	21223	Rags, Roots, Trash	Wet		0	Heavy gray water observed around the cleanout at the rear of the property.	3	Relieved 6" house connection choke with 45 ft of electric cable.	Confirmed mainline and lateral are clear.	511234
10	1/16/2018	5601 Purlington Way	21212	Rags, Roots, Trash	Dry		60	Wastewater overflowing into adjacent storm drain; found during routine sampling.	300	Relieved 8" mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	512695
11	1/17/2018	1202 Cochran Ave	21239	Roots, Grease, Trash	Dry	Herring Run	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	513590
12	1/17/2018	Queensberry Ave & W Garrison Ave - SSO #135	21215	Grease	Dry	Jones Falls	2,585	Structured overflow discharging to a nearby storm drain.	150,000	Relieved mainline choke.	Confirmed mainline is clear and back to regular flow.	
13	1/18/2018	5601 Purlington Way	21212	Trash	Dry		63	Choked mainline causing overflow into adjacent storm drain; found during routine sampling.	32	Flushed and cleaned 8" mainline with 300 ft of pressure hose.	Performed CCTV inspection.	514074
14	1/19/2018	Edmondson Ave & Hilton Pkwy	21229	Rags, Grease, Trash	Dry		495	Heavy gray water escaping manhole in the street.	2,475	Relieved 8" mainline choke with 150 ft of pressure hose.	Performed mainline CCTV inspection.	514340
15	1/21/2018	2708 Woodland Ave	21215	Rags, Grease, Trash	Dry		100	Heavy gray water overflowing from three house connections.	1,000	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	515339
16	1/22/2018	5601 Purlington Way	21212	Roots	Dry		53	Choked sanitary pipe overflowing into adjacent storm pipe; found during routine sampling.	265	Relieved mainline choke with pressure hose.	Performed CCTV inspection.	515817
17	1/22/2018	8 Midvale Rd	21210	Structural	Dry		0	Gray water observed around the cleanout, no further leaking from damaged pipe.	15	House lateral repair underway.	Performed CCTV inspection.	515899
18	1/24/2018	2218 Hillhouse Rd	21207	Rags, Roots, Grease	Wet		43	Heavy gray water escaping the manhole in the street.	215	Relieved 8" mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear.	516399
19	1/24/2018	3200 Carlisle Ave	21216	Rags, Grease, Trash	Wet	Gwynns Falls	146	Choked sanitary mainline causing overflow into adjacent storm drain.	730	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	516540

