

SSO Notification List

August 2022

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	8/1/2022	204 E Chase St	21202	Rags, Grease	Wet	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed the lateral is now clear.	1124738
2	8/1/2022	4311 Willshire Ave	21206	Rags, Roots, Grease	Wet	N/A	239	Mainline choke causing subsurface SSO; infiltrating storm drain.	2,390	Relieved mainline choke with 200 ft of pressure hose.	Abatement confirmed via the Office of Compliance and Research.	1124798
3	8/1/2022	2301 Washington Blvd	21230	Rags, Roots, Grease	Wet	Gwynns Falls	1481	Gray water escaping the manhole.	14,810	Relieved mainline choke with 400 ft of pressure hose.	Confirmed the mainline is now clear.	1124949
4	8/1/2022	3527 Gelston Dr	21229	Rags, Roots, Grease	Wet	Gwynns Falls	83	Heavy gray water escaping the manhole.	8,300	Relieved mainline choke with 100 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1124889
5	8/3/2022	3527 Gelston Dr	21229	Rags, Roots, Rain	Wet	Gwynns Falls	1320	Heavy gray water escaping manhole stack.	66,000	Relieved mainline choke with 500 ft of pressure hose.	CCTV inspection will be performed on the mainline.	1125914
6	8/8/2022	1807 W Rogers Ave	21209	Roots, Grease	Dry	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Performed lateral CCTV inspection.	1127261
7	8/9/2022	3527 Gelston Dr	21229	Rags, Roots, Rain	Wet	Gwynns Falls	1455	Manhole surcharging into nearby stream.	72,750	Relieved mainline choke with 500 ft of pressure hose.	Confirmed this section of the line is now clear.	1127418
8	8/9/2022	1608 Aisquith St	21202	Roots	Dry	N/A	—	Gray water observed at the front of the property.	1	Relieved house connection choke with 65 ft of electric cable.	Asset will be placed on routine root control.	1127472
9	8/10/2022	3500 Parkdale Ave	21211	Other	Wet	Jones Falls	1565	Sewage pump stopped operating causing sump basin to overflow into storm pipe.	1,565	Pump discharge hose malfunction was fixed.	Long term fix is still being implemented at this location.	—
10	8/13/2022	1719 W Lexington St	21223	Sand, Gravel, Rocks, Unknown	Wet	N/A	—	Gray water observed around the cleanout.	1	Ran 45 ft of electric cable through the lateral; blockage remained.	CCTV will be performed to determine cause of issue.	1128900
11	8/14/2022	1528 N Caroline St	21213	Structural, Other	Dry	N/A	—	Gray water observed at the front of the property.	1	Ran 15 ft of electric cable through the lateral. Determined line is damaged.	Lateral will be repaired to restore regular functionality.	1128927
12	8/18/2022	1529 Edmondson Ave	21223	Rags, Trash	Wet	N/A	—	Gray water observed around the cleanout.	2	Relieved house connection choke with 60 ft of electric cable.	Lateral CCTV inspection will be performed.	1131058
13	8/22/2022	302 E Belvedere Ave	21212	Rags, Roots	Dry	N/A	—	Gray water observed at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	1131965
14	8/25/2022	2723 Presbury St	21216	Rags, Roots	Dry	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and confirmed the lateral is clear.	1133002
15	8/29/2022	3714 Fairhaven Ave	21226	Rags, Trash	Dry	N/A	—	Gray water escaping from a sump pump.	3	Relieved mainline choke with 300 ft of pressure hose.	Mainline CCTV inspection will be performed.	1133873
16	8/30/2022	529 N Linwood Ave	21205	Rags, Grease, Trash	Dry	N/A	—	Gray water observed around the manhole.	5	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is clear; CCTV inspection will be performed.	1133960
				# WWO	9			TOTAL	165,833	UNDER 100 GALLONS	10	