

SSO Notification List

February 2022

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	2/1/2022	2528 Insulator Dr	21230	Rags, Grease	Dry	N/A		Gray water observed around the manhole.	5	Relieved mainline choke with 250 ft of pressure hose.	Confirmed mainline is now clear; CCTV inspection will be performed.	1016040
2	2/1/2022	1227 Park Ave	21217	Rags, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with electric cable and pressure hose.	Confirmed the lateral is now clear; mainline will be cleaned.	1016074
3	2/2/2022	1831 W Saratoga St	21223	Rags, Sand, Gravel, Rocks	Dry	N/A	662	Gray water observed around the manhole in the alley.	5	FLUSH & RELIEVED M/L CHOKE WITH PRESS TRUCK 200 FT OF 6"INCH	Further investigation, including CCTV inspection, will take place.	1015102
4	2/2/2022	3114 Cedarhurst Rd	21214	Rags, Roots, Grease, Trash	Dry	Herring Run	171	Sewage escaping the manhole and entering nearby storm drain.	855	Relieved mainline choke with 50 ft of pressure hose.	Confirmed the line is clear; CCTV inspection will be performed.	1016445
5	2/2/2022	424 Calvin Ave	21218	Unknown	Dry	N/A		Gray water observed around the cleanout.	1	Ran 75 ft of electric cable through the lateral; blockage remained.	Further investigation, including a CCTV inspection, will take place.	1016588
6	2/3/2022	3920 Potee St	21225	Rags, Grease	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is clear and flowing freely at this time.	1016904
7	2/5/2022	102 W Madison St	21201	Rags	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Lateral CCTV inspection will be performed.	1017251
8	2/7/2022	1267 Riverside Ave	21230	Rags	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed.	1017449
9	2/7/2022	1251 E Northern Pkwy	21239	Rags, Grease	Dry	Herring Run	146	Gray water escaping the manhole.	584	Relieved 8" mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed to confirm the line clear.	1017499
10	2/9/2022	1605 Saint Paul St	21202	Rags	Dry	N/A		Gray water observed around the manhole.	3	Relieved mainline choke with 300 ft of pressure hose.	Further investigation will take place to determine if system is clear.	1018216
11	2/9/2022	4727 Old York Rd	21212	Rags, Grease	Dry	Tiffany Run	116	Gray water escaping sewage system and entering nearby storm drain.	29	Relieved mainline choke with 320 ft of pressure hose.	CCTV inspection will be performed.	1018239
12	2/9/2022	5204 Liberty Heights Ave	21207	Rags, Grease	Dry	Gwynns Falls	46	Sewage overflowing into adjacent storm drain.	2,300	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is now clear; CCTV inspection will be performed.	1018294
13	2/9/2022	4505 Seminole Ave	21229	Rags, Roots, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 300 ft of pressure hose.	Confirmed the lateral is now clear; CCTV will be performed.	1018337
14	2/9/2022	100 W Barre St	21201	Roots	Dry	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1018444
15	2/10/2022	Edgevale Rd & Elmwood Rd	21210	Rags, Roots, Grease	Dry	Jones Falls	135	Gray water escaping the manhole in the street.	270	Relieved mainline choke with 100 ft of pressure hose.	Confirmed the 6" mainline is now flowing freely.	1018474
16	2/11/2022	702 N Carrollton Ave	21217	Rags, Unknown	Dry	N/A		Gray water observed around the cleanout.	1	Ran 45 ft of electric cable through the lateral; blockage remained.	Pumping and lateral launch will need to be performed.	1018754
17	2/12/2022	2103 Mount Holly St	21216	Rags, Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is clear; CCTV inspection will be performed.	1019010
18	2/16/2022	251 S Morley St	21229	Rags, Roots, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear.	1019777
19	2/17/2022	12 Beechdale Rd	21210	Rags, Roots, Grease	Dry	Jones Falls	2465	Choked sanitary sewer overflowing into adjacent storm pipe.	61,625	Relieved 6" mainline choke with 300 ft of pressure hose.	Confirmed the line is clear at this time; CCTV inspection will be performed.	1020244
20	2/17/2022	500 W University Pkwy	21210	Rags, Roots, Grease	Dry	N/A	1925	Gray water escaping the manhole.	28,875	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1020183
21	2/17/2022	1927 Division St	21210	Structural	Wet	N/A	7120	Gray water escaping the manhole at the rear of the property.	7,120	Set up bypass pumping to stop the overflow.	Mainline will need to be repaired to address structural damage.	1020266
22	2/17/2022	3305 Burleith Ave	21215	Structural	Wet	N/A		Gray water observed around the cleanout.	1	Ran 37 ft of electric cable through the lateral.	Advised consumer to have plumber inspect their side of the line.	1020288
23	2/18/2022	3004 Howard Park Ave	21207	Roots	Wet	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed both lateral and mainline are now clear.	1020446
24	2/18/2022	4015 Bonner Rd	21216	Structural	Wet	N/A		Gray water and debris observed at the cleanout.	1	Ran 30 ft of electric cable through the lateral.	Repair will need to be made to lateral to address structural damage.	1020555
25	2/19/2022	305 E University Pkwy	21218	Rags, Roots	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed.	1020632

SSO Notification List

February 2022

26	2/20/2022	5001 Hillen Rd	21239	Rags, Trash	Wet	N/A		Gray water observed around the manhole.	2	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the mainline is clear; CCTV will be performed.	1020703
27	2/21/2022	2111 Garrison Blvd	21216	Rags, Roots, Trash	Dry	Gwynns Falls	1625	Gray water escaping the manhole.	1,625	Partially relieved mainline choke with 300 ft of pressure hose.	CCTV inspection showed roots in the pipe that will cut and removed.	1020769
28	2/23/2022	1404 Ramsay St	21223	Rags, Roots, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Lateral CCTV inspection will be performed.	1021182
29	2/23/2022	4302 Maine Ave	21207	Rags	Dry	N/A		Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Confirmed both the lateral and mainline are clear.	1021260
30	2/23/2022	3600 Plateau Ave	21207	Sand, Gravel, Rocks, Structural	Dry	N/A		Gray water observed around the cleanout.	2	Ran 20 ft of electric cable through the lateral.	Determined lateral will need structural repair.	1021426
31	2/23/2022	4517 Schenley Rd	21210	Rags, Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 90 ft of electric cable.	CCTV inspection and mainline cleaning will be performed.	1021434
32	2/24/2022	1601 S Haven St	21224	Structural	Dry	N/A		Gray water observed around the cleanout.	3	Partially relieved choke; determined structural damage exists in the pipe.	Office of Engineering and Construction will repair the mainline.	1021457
33	2/24/2022	3224 Woodhome Ave	21234	Rags, Trash	Dry	Moores Run	1190	Choked mainline causing overflow into adjacent storm drain pipe.	5,950	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now clear at this time.	1021589
34	2/24/2022	2132 Bolton St	21217	Grease, Unknown	Dry	N/A		Gray water and debris around the cleanout.	1	Ran 60 ft of electric cable through the lateral; blockage remained.	Further investigation, including lateral launch and CCTV inspection, will take place.	1021621
35	2/27/2022	2816 W North Ave	21216	Rags	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Lateral CCTV inspection will be performed.	1021946
36	2/28/2022	4906 Westhills Rd	21229	Rags	Wet	N/A		Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed both the lateral and mainline are now clear.	1021975
37	2/28/2022	3400 Chesley Ave	21234	Rags, Grease, Infiltration, Trash	Wet	Moores Run	1634	Choked mainline causing overflow into storm pipe.	8,170	Relieved mainline choke with 250 ft of pressure hose.	Performed CCTV inspection and results showed the line to be clear.	1022041
				# WWO	11			TOTAL	117,443	UNDER 100 GALLONS	27	