

SSO Notification List

January 2023

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	1/1/2023	Clifton Rd & Mondawmin Ave	21216	Rags, Trash	Wet	N/A		Gray water observed on the sidewalk and street.	2	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed.	1167002
2	1/1/2023	611 Edgevale Rd	21210	Roots	Wet	N/A		Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Confirmed the lateral is clear at this time.	1167011
3	1/2/2023	3300 Windsor Ave	21216	Rags, Trash	Wet	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed.	1167060
4	1/3/2023	4414 Pen Lucy Rd	21229	Rags, Structural	Wet	N/A		Gray water observed around the cleanout.	1	Ran electric cable through the lateral; determined structural damage exists.	Pipe will need to be repaired to restore regular functionality.	1167162
5	1/4/2023	2802 Frederick Ave	21223	Rags, Roots, Grease	Dry	Gwynns Falls	60	Gray water escaping the manhole and entering stream.	180	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is clear; CCTV inspection will be performed.	1167522
6	1/5/2023	3600 Labyrinth Rd	21215	Rags, Grease	Dry	N/A	138	House connection choke causing subsurface wastewater infiltration into the storm drain.	276	Relieved house connection and mainline chokes with electric cable and pressure hose.	Lateral CCTV confirmed the line is clear.	1168025
7	1/5/2023	4719 York Rd	21212	Rags, Grease	Dry	Tiffany Run	1391	Choked sanitary sewer overflowing into adjacent storm pipe.	1,391	Relieved mainline choke with 40 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1168065
8	1/5/2023	1831 S Charles St	21230	Rags, Grease, Trash	Dry	N/A	150	Gray water escaping the cleanout.	30	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the mainline is now clear, giving relief to cleanout.	1168073
9	1/5/2023	2213 Annapolis Rd	21230	Roots	Dry	N/A		Gray water observed around the cleanout.	2	Relieved house connection choke with 30 ft of electric cable.	Flushed and cleaned the mainline; confirmed lines are clear.	1168164
10	1/6/2023	2803 Elgin Ave	21216	Rags, Roots, Grease	Dry	Gwynns Falls	50	Gray water escaping a side house connection.	25	Relieved house connection choke with 200 ft of pressure hose.	Performed CCTV inspection and cleaned the mainline.	1168260
11	1/6/2023	611 S Monroe St	21223	Sand, Gravel, Rocks	Dry	N/A		Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 35 ft of electric cable.	Left door notice with information; advised consumer to install cleanout cap.	1168396
12	1/8/2023	5615 York Rd	21212	Rags, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral and mainline are both now clear.	1168512
13	1/8/2023	5516 Frankford Ave	21206	Rags, Grease	Dry	N/A		Gray water observed near the manhole at the rear of the property.	5	Relieved mainline choke with 400 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1168515
14	1/8/2023	3314 Oakfield Ave	21207	Rags	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 75 ft of electric cable.	Lateral CCTV inspection will be performed.	1168521
15	1/10/2023	6300 Boston St	21224	Grease	Dry	Inner Harbor	140	Heavy gray water escaping the manhole in the street.	2,800	Used high-pressure jet truck to relieve mainline choke. Flushed and cleaned 8" pipe.	CCTV inspection will determine further steps to be taken.	1169006
16	1/10/2023	1810 W Lombard St	21223	Rags, Grease	Dry	N/A		Water and paper observed near the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed.	1168990
17	1/10/2023	16 Elmwood Rd	21210	Rags, Roots, Grease	Dry	N/A		Gray water observed around the manhole.	3	Relieved mainline choke with 250 ft of pressure hose.	Confirmed the mainline is clear; CCTV inspection will be performed.	1168994
18	1/10/2023	3330 Henry G Parks Jr Cir	21215	Rags, Trash	Dry	N/A		Gray water and debris observed near the manhole.	2	Relieved mainline choke with 350 ft of pressure hose.	Confirmed line is flowing freely. CCTV will be performed.	1169101
19	1/11/2023	4714 Holabird Ave	21222	Rags, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection and results showed the line is now clear.	1169422
20	1/12/2023	1801 N Payson St	21217	Rags, Grease	Dry	Gwynns Falls	121	Gray water escaping from the manhole at the rear of the property.	605	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the mainline is clear; CCTV inspection will be performed.	1169806

SSO Notification List

January 2023

21	1/12/2023	2738 Baker St	21216	Rags	Dry	N/A		Gray water and debris observed on the ground.	2	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed.	1169608
22	1/12/2023	3505 Lyndale Ave	21213	Rags, Roots, Trash	Dry	N/A		Gray water observed around the cleanout at this location.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is now clear.	1169707
23	1/15/2023	Clifton Rd & Mondawmin Ave	0	Rags, Roots, Trash	Wet	N/A		Water and sewage observed around the lamphole in the street.	5	Relieved mainline choke with pressure hose.	Confirmed the line and lamphole are no longer choked.	1169974
24	1/16/2023	2500 W Fayette St	21223	Rags, Grease, Sand, Gravel, Rocks	Dry	Gwynns Falls	3105	Gray water escaping the manhole in the street near storm drain.	3,105	Relieved heavy mainline choke blockage with pressure hose after multiple attempts.	Confirmed the mainline is now clear at this location.	1170014
25	1/16/2023	1203 Morling Ave	21211	Grease	Dry	N/A		Sewage and water observed around the manhole.	2	Relieved mainline choke with 35 ft of pressure hose.	Confirmed the line is now clear; CCTV will be performed.	1170066
26	1/17/2023	1511 E 29th St	21218	Rags, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection to confirm the line is clear.	1170450
27	1/23/2023	4613 Wallington Ave	21215	Rags, Grease	Wet	N/A		Mainline choke causing sump pump to overflow.	2	Relieved choke with 200 ft of pressure hose.	Confirmed lines are now clear.	1182596
28	1/23/2023	E Belvedere Ave & Clearspring Rd	21212	Sand, Gravel, Rocks	Wet	N/A		Sewer water coming from manhole	5	Relieved mainline choke with 50 ft of pressure hose.	Confirmed the line is now clear at this time.	1182822
29	1/25/2023	5101 Roland Ave	21210	Roots	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	1192856
30	1/26/2023	436 Kane St	21224	Rags, Grease	Wet	Inner Harbor	950	Gray water and debris escaping the manhole.	950	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed.	1193031
31	1/26/2023	5916 York Rd	21212	Rags, Grease	Wet	Chinquapin Run	453	Sewer overflowing into adjacent storm drain pipe.	45,300	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed.	1193120
32	1/27/2023	115 S Stricker St	21223	Rags, Trash	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral and mainline are clear.	1193442
33	1/28/2023	429 Westgate Rd	21229	Roots	Wet	N/A		Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection confirmed the lateral is now clear.	1193554
34	1/30/2023	5908 The Alameda	21239	Rags, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection to confirm the lateral is clear.	1193764
35	1/30/2023	1642 Ashburton St	21216	Roots, Grease, Trash	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1193818
				# WWO	12			TOTAL	54,707	UNDER 100 GALLONS	27	