

SSO Notification List

June 2022

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	6/1/2022	319 N Payson St	21223	Rags, Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	1108069
2	6/1/2022	1522 N Fulton Ave	21217	Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are now clear.	1108088
3	6/2/2022	924 Newington Ave	21217	Rags, Trash, Sand, Gravel, Rocks, Structural	Dry	N/A		Gray water observed at the rear of the property.	1	Ran 15 ft of electric cable through the lateral; issues remain.	Further action, including lateral repair and bypass pumping may be required.	1108567
4	6/7/2022	2508 Queen Anne Rd	21216	Sand, Gravel, Rocks, Structural	Dry	Gwynns Falls	348	Gray water escaping the manhole.	1,044	Used pressure hose to flush the mainline. Discovered damage to pipe.	Repair will take place to restore line to regular functionality.	1109385
5	6/7/2022	1724 E Lanvale St	21213	Sand, Gravel, Rocks, Structural	Dry	N/A		Gray water observed around the manhole.	2	Partially relieved choke by flushing line with pressure hose.	Further investigation will take place to determine if structural damage exists in the pipe.	1109514
6	6/8/2022	824 E Fort Ave	21230	Sand, Gravel, Rocks	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; informed consumer to install cleanout cap.	1109743
7	6/8/2022	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	N/A	30	Structure monitored by metered equipment in the pipe. Not visually observed.	5,010	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	
8	6/8/2022	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	25	Structure monitored by metering equipment in the pipe.	7,000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	
9	6/8/2022	N Charles St & W Lanvale St - SSO Site #152	21201	Rain	Wet	Jones Falls	25	Structure monitored by metered equipment in the pipe. Not visually observed.	9,000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	
10	6/8/2022	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	45	Structure monitored by metering equipment in the pipe. Not visually observed.	141,030	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	
11	6/8/2022	3900 Belair Rd	21206	Rain	Wet	Herring Run	70	Manhole adjacent to creek overflowed due to heavy rain.	147,000	Overflow subsided following heavy rain event.	Overflow will be prevented after completion of capital improvement projects.	
12	6/8/2022	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	60	Structure monitored by metering equipment in the pipe. Not visually observed.	65,040	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	
13	6/10/2022	3400 Carlins Park Dr	21215	Rags, Rain	Wet	Gwynns Falls		Wastewater debris scattered around manhole; likely result of recent storm.	1,000	Flushed and cleaned the mainline with pressure hose.	CCTV inspection will be performed to ensure the line is clear.	1110537
14	6/10/2022	2105 Hollins Ferry Rd	21230	Rags, Roots	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 40 ft of pressure hose.	Confirmed both the lateral and mainline are now clear.	1110623
15	6/13/2022	311 Somerset Rd	21210	Rags, Roots	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection and results showed the line is now clear.	1110890
16	6/13/2022	3205 Fairfield Rd	21226	Rags, Grease	Wet	N/A		Gray water observed around the manhole.	2	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the mainline is clear at this time.	1110898
17	6/13/2022	3458 Park Heights Ave	21215	Structural	Wet	N/A		Gray water and debris around the cleanout.	1	Ran 12 ft of electric cable through the lateral.	Advised consumer to have pipe inspected.	1111219
18	6/21/2022	714 Brookwood Rd	21229	Rags, Grease	Dry	N/A	82	Gray water escaping the manhole in the street.	82	Relieved mainline choke with 200 ft of pressure hose.	Confirmed line is flowing freely; CCTV inspection will be performed.	1112867
19	6/21/2022	1018 McDonogh St	21205	Rags, Grease, Trash	Dry	N/A		Gray water observed in the rear alley.	3	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1112986
20	6/25/2022	1801 N Payson St	21217	Rags, Trash	Wet	N/A		Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and confirmed the lateral and mainline are clear.	1113997

SSO Notification List

June 2022

21	6/27/2022	1152 Shields Pl	21201	Roots	Wet	N/A		Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed lateral and mainline are clear.	1114371
22	6/28/2022	2621 Talbot Rd	21216	Rags, Roots	Wet	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection and mainline cleaning will be performed.	1114548
23	6/28/2022	4312 Willshire Ave	21206	Rags, Roots, Grease	Wet	N/A	116	Subsurface SSO infiltrating the nearby storm drain system.	1,160	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1114651
24	6/29/2022	1920 Orleans St	21231	Rags, Trash	Wet	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 90 ft of electric cable.	Performed lateral CCTV inspection.	1113854
25	6/29/2022	1030 Ashland Ct	21202	Rags, Grease	Wet	N/A		Gray water observed around the manhole.	2	Relieved 8" mainline choke with 300 ft of pressure hose.	Confirmed the line is now clear; CCTV will be performed.	1114801
26	6/29/2022	1719 W Lexington St	21223	Rags, Sand, Gravel, Rocks	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection and mainline cleaning will take place.	1114805
27	6/30/2022	2512 Southdene Ave	21230	Structural	Dry	N/A		Gray water observed at the front of the property.	1	Discovered structural damage exists in the lateral.	House connection will need to be repaired.	1115908
				# WWO	19			TOTAL	377,388	UNDER 100 GALLONS	18	