

SSO Notification List

May 2023

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	5/1/2023	4507 Roland Ave	21210	Rags, Roots, Trash	Wet	N/A		Gray water observed around the manhole in the street.	2	Relieved mainline choke with 350 ft of pressure hose.	CCTV inspection will be performed to determine if further work is needed.	1218656
2	5/1/2023	2812 Hinsdale Dr	21230	Trash, Structural	Wet	N/A		Gray water observed at the front of the property.	1	Flushed and cleaned 8" mainline; lateral will need to be fixed.	CCTV inspection will be performed to determine further steps.	1218667
3	5/1/2023	2210 Lyndhurst Ave	21216	Roots, Trash	Wet	N/A		Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is now clear.	1218853
4	5/1/2023	2152 Hollins St	21223	Sand, Gravel, Rocks, Unknown	Wet	N/A		Gray water observed at the rear of the property.	1	Ran electric cable through the lateral; blockage remained.	Further investigation, including CCTV inspection, will be performed.	1218864
5	5/1/2023	1612 Elmtree St	21226	Structural	Wet	N/A		Sewage observed around the cleanout.	1	Ran electric cable through the lateral; determined structural damage exists.	Further investigation, including CCTV inspection, will be performed to determine next steps.	1218862
6	5/2/2023	2803 Elgin Ave	21216	Rags, Grease	Wet	N/A		Gray water and debris observed at the rear of the property.	1	Relieved house connection choke with 200 ft of pressure hose.	Confirmed the lateral and mainline are both clear.	1219087
7	5/3/2023	Edmondson Ave & Hilton St	21229	Rags, Roots, Grease	Dry	Gwynns Falls	1560	Sewage escaping the manhole and reaching waterway.	15600	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed to determine if further action is needed.	1219722
8	5/5/2023	642 E Clement St	21230	Rags, Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	1220526
9	5/8/2023	1403 Race St	21230	Rags, Trash	Dry	N/A		Gray water and paper observed around the cleanout.	1	Relieved choke with pressure hose.	CCTV inspection will be performed.	1221213
10	5/9/2023	Eastern Pkwy & Glenmore Ave	21206	Rags, Infiltration, Trash	Dry	Herring Run	675	Pipe segment exfiltrating subsurface into storm drain while backed up from downstream choke.	675	Relieved 10" mainline choke with 250 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1221441
11	5/9/2023	1612 Elmtree St	21226	Rags, Roots	Dry	N/A		Gray water escaping cleanout and entering storm drain.	5	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection will be performed to determine if further action is needed.	1221467
12	5/11/2023	4305 Wendover Rd	21218	Rags, Trash	Dry	Stony Run	140	Sanitary sewer overflowing into adjacent storm pipe.	700	Used high-pressure jet truck to relieve mainline choke, flushed and cleaned 8" sanitary mainline.	CCTV inspection will determine if further steps are needed.	1222380
13	5/12/2023	N Athol Ave & Birchwood Dr	21229	Rags, Roots, Grease	Dry	Gwynns Falls	147	Sewage escaping manhole and entering storm drain inlet.	1470	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1223524
14	5/15/2023	5002 Boxhill Ln	21210	Rags, Roots	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 75 ft of electric cable.	CCTV confirmed the lateral is now clear.	1223890
15	5/15/2023	2303 James St	21230	Structural	Wet	N/A	2832	Leak from broken sewer pipe.	708	Repaired broken mainline to restore system to regular functionality.	Abatement confirmed via the Office of Research & Environmental Protection.	1223937
16	5/17/2023	2803 Elgin Ave	21216	Sand, Gravel, Rocks, Unknown	Dry	N/A	250	Gray water escaping the cleanout.	25	Ran electric cable through the lateral; blockage remained.	CCTV inspection will determine whether further action is needed.	1225040
17	5/19/2023	1203 Mosher St	21217	Rags, Roots, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	CCTV confirmed the lateral and mainline are clear.	1225402
18	5/20/2023	Elizabeth Ave & Harriet Ave	21230	Rags, Grease	Dry	Gwynns Falls	1741	Gray water escaping the manhole in the street.	3482	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	1225607
19	5/20/2023	3520 Beech Ave	21211	Rags, Roots, Grease	Dry	Stony Run	3118	Sewage escaping the manhole and reaching a waterway.	3118	Relieved mainline choke with 100 ft of pressure hose.	Confirmed the line is now clear; CCTV will be performed.	1225632
20	5/21/2023	3221 Clarks Ln	21215	Rags, Trash	Wet	N/A	240	Gray water escaping the manhole.	120	Relieved mainline choke with 100 ft of pressure hose.	Confirmed mainline is clear; CCTV will be performed.	1225608

SSO Notification List

May 2023

21	5/22/2023	4407 St Georges Ave	21212	Rags, Trash	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	1225955
22	5/26/2023	1111 Bellemore Rd	21210	Rags, Roots	Dry	N/A		Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; CCTV will be performed.	1227091
23	5/28/2023	6014 Bertram Ave	21214	Rags, Roots	Dry	N/A		Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	1227161
24	5/29/2023	301 Edgevale Rd	21210	Rags, Roots	Dry	N/A		Gray water observed at the front of the property.	1	Ran 60 ft of electric cable through the lateral; flushed and cleaned the mainline.	CCTV inspection will be performed to determine if further action is needed.	1227200
25	5/30/2023	445 W 24th St	21211	Rags, Roots, Grease	Dry	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and results showed the line is clear.	1227300
26	5/30/2023	2800 Rosalind Ave	21215	Rags, Roots, Rain	Dry	N/A		Gray water and rags observed around the cleanout.	10	Relieved house connection choke and flushed and cleaned the mainline.	CCTV inspection will be performed to determine if further action is needed.	1227560
				# WWO	9			TOTAL	25,929	UNDER 100 GALLONS	18	