

SSO Notification List

November 2022

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	11/3/2022	5312 Brabant Rd	21229	Roots	Dry	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the mainline.	1151723
2	11/3/2022	901 Allendale St	21229	Rags, Roots, Grease, Sand, Gravel, Rocks	Dry	Gwynns Falls	1515	Heavy gray water escaping the manhole.	303,000	Relieved multiple chokes in 12" mainline with 300 ft of pressure hose.	Confirmed the pipe segments are now clear; CCTV will be performed.	1151872
3	11/6/2022	1214 Homewood Ave	21202	Rags	Dry	N/A	—	Gray water observed near the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection to confirm line is clear.	1152386
4	11/9/2022	2301 Washington Blvd	21230	Rags, Roots, Grease	Dry	Gwynns Falls	126	Gray water escaping the manhole.	1,260	Relieved mainline choke with 300 ft of pressure hose.	Mainline CCTV inspection and cleaning will take place.	1153550
5	11/13/2022	606 Winston Ave	21212	Structural	Wet	Tiffany Run	4068	Heavy gray water escaping the manhole.	40,680	Flushed the mainline, but discovered break in the pipe. Set up bypass pumping to stop the overflow.	Mainline repair will restore system to regular functionality.	1154609
6	11/14/2022	2403 Westport St	21230	Rags	Wet	N/A	—	Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1154888
7	11/14/2022	1412 N Luzerne Ave	21213	Rags, Trash	Wet	N/A	—	Gray water observed at the front of the property.	1	Relieved house connection choke with 40 ft of electric cable.	Confirmed the lateral is clear at this time.	1154908
8	11/14/2022	2118 Maryland Ave	21218	Roots	Wet	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed both the lateral and mainline are clear.	1154959
9	11/14/2022	4600 Hampnett Ave	21214	Rags, Trash	Wet	N/A	—	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection to confirm the lateral is clear.	1154960
10	11/15/2022	1629 N Montford Ave	21213	Sand, Gravel, Rocks, Structural	Dry	N/A	—	Gray water observed at the rear of the property.	2	Ran 27 ft of electric cable through the lateral to partially relieve choke. Determined structural damage exists to lateral.	House connection will be repaired. Bypass pump may be necessary while work is performed.	1155266
11	11/15/2022	3900 Belair Rd	21206	Rain	Wet	Herring Run	50	Manhole adjacent to creek overflowed due to heavy rain.	109,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	N/A
12	11/21/2022	1412 N Luzerne Ave	21213	Roots	Dry	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Advised consumer to install cleanout cap.	1156810
13	11/21/2022	Chinquapin Pkwy & Harwood Ave	21239	Rags, Trash	Dry	N/A	—	Gray water observed around the manhole.	2	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the mainline is now clear; CCTV inspection will be performed.	1157089
14	11/22/2022	1612 S Hanover St	21230	Rags, Grease	Dry	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed both the lateral and mainline are clear.	1157110
15	11/22/2022	2535 Ashton St	21223	Rags, Grease, Trash	Dry	N/A	—	Gray water and debris observed on the street.	2	Relieved mainline choke with 135 ft of pressure hose.	Confirmed the mainline is now clear at this time.	1157154
16	11/23/2022	3900 Emmart Ave	21215	Rags, Grease, Trash	Dry	Gwynns Falls	52	Subsurface SSO discovered during routine sampling.	520	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed to ensure system is functioning normally.	1157515
17	11/29/2022	14 Saint Martins Rd	21218	Roots	Wet	Jones Falls	185	Mainline choke causing wastewater to infiltrate the storm drain subsurface.	3,700	Relieved mainline choke with 140 ft of pressure hose.	CCTV inspection will be performed to determine if further action is needed.	1158375
				# WWO	7				TOTAL	458,174	UNDER 100 GALLONS	11